



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

September 9, 2008

Peter Allred
Ultradent Products
505 W 10200 S
South Jordan, Utah 84095

Re: Denial of Request to Close File, Ultradent products; Ultrdent Claims; S0450057; Uintah County, Utah

Dear Mr. Ginton:

On March 20, 2007, we received your request to inspect and close the Ultradent O C Claim files. This letter is to notify you that your request is being denied. An inspection performed on May 14, 2008, indicated that no reclamation has not been initiated; therefore, according to rule, we are unable to release the site at this time.

It is our recommendation that you remove trash, regrade the site to natural contour, spread topsoil, implement a noxious weed program, and apply seed mix until the revegetation standard is achieved. Photo documentation of each of the sites is attached in each of the inspection report.

Permit fees are delinquent. The annual fees remain due and are payable within 30 days. Another billing statement is enclosed for this purpose. When the site meets the required reclamation standards, you may again notify us in writing requesting release of the project.

If you have any questions or concerns regarding this action, please contact me at (801) 538-5320 or Leslie Heppler (801) 538-5257. We hope the site will be ready for release this coming spring.

Sincerely,

Dana Dean, P.E.
Associate Director - Mining

DD:lah;eb

Enclosure: Billing Statements, Inspection Reports

TASK # 1743

cc: SITLA - Will Stoke: BLM - Larry Garahana, Stephen Allen

O:\M045-Tooele\S0450057-Ultradent\final\deny-release_S0450057.doc





JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
May 28, 2008

Reviewed _____

Mine Name: Ultradent O C Claims	Permit Number: S0450057
Operator Name: Ultradent Products	Inspection Date: May 14, 2008
Inspector(s): L Heppler	Time: 12:30pm
Other Participants: None	Mine Status: INS

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: None listed **Bond Amount:** \$ None listed. **Permit Fee** is delinquent – need to pay fee by June 30, 2008 or reclaim ground.

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Data base indicates this site has been active in previous years but never been inspected. See map for access. No signs of recent activity. Trailer with satellite dish and fenced area are on site. Open portal and pad area are less than 1 acre. Open Portal is a safety hazard. Every effort should be made to salvage top soil from the site prior to mining. No topsoil stockpile were noted on site. There has been no reclamation or regrading started on the site. There is trash that needs to be removed from the site.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator has 30 days to comply with all local, state and federal rules, including, but not limited to the unsafe portal and rockfall hazard at the portal opening. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:pb

cc: Peter Allred

Larry Garahana – BLM, Will Stokes - SITLA)

Attach - GIS

File Name and Path

Photos Taken 05-14-08

